





# 機械螺絲規格表




## MACHINE SCREW SIZE



SM MACHINE SCREW 2A (山形60°)					
SM 針車用螺紋規格					
SIZE 規格	T 牙數	外徑(D)		軋造徑(d)	
		最大(MAX)	最小(MIN)	最大(MAX)	最小(MIN)
5/16	64	1.984	1.904	1.71	1.69
3/32	56	2.381	2.306	2.07	2.04
1/8	48	3.175	3.065	2.81	2.78
1/8	44	3.175	3.055	2.78	2.75
1/8	40	3.175	3.045	2.74	2.71
9/64	40	3.572	3.442	3.13	3.10
11/64	40	4.366	4.236	3.92	3.89
11/64	32	4.366	4.206	3.82	3.79
3/16	40	4.762	4.632	4.32	4.29
3/16	32	4.762	4.602	4.22	4.19
3/16	28	4.762	4.602	4.14	4.11
3/16	24	4.762	4.602	4.04	4.01
13/64	32	5.159	4.999	4.60	4.57
7/32	32	5.556	5.396	5.01	4.98
15/64	28	6.953	5.773	5.32	5.29
1/4	40	6.350	6.220	5.90	5.87
1/4	28	6.350	6.170	5.72	5.69
1/4	24	6.350	6.170	5.62	5.59
9/32	28	7.144	6.954	6.51	6.48
9/32	20	7.144	6.954	6.28	6.25
5/16	24	7.938	7.748	7.21	7.18
5/16	18	7.938	7.748	6.98	6.94



### \*機械牙板調機注意事項



\*裝置牙板調機時，以商標相對為優先使用面。  
當一面損壞後，再反商標方向裝置調機。